

nMotion Mach3 USB Motion Card Installation Manual


Features:

- Fully supporting all Mach3 versions, including the Mach3 R3.043.066 version.
- Supporting Windows series, including Windows2000/XP/Vista/Win7/Win8/Win10.
- No need to install any USB drivers,it can be used aftr plugging in the computer.
- USB bus is the use of magnetic coupling isolation, isolation of real value, different from the general control card optocoupler input and output, do high reliability, absolute guarantee the safety of the computer USB. At the same time to ensure that the strong anti-interference ability of EMC.
- The single chip, the system stability is more streamlined, multi chip processing generally incomparable
- Dual core ultra - high speed CPU (the maximum single core frequency 204MHz), operation processing ability has great redundancy, and ensure the realization of four axis linkage under1500KHz frequency of the pulse output, 6 axis pulse output frequencies up to 800kHz, connected to the servo / step
- Motion control buffer size can be set and ensure the fast interpolation cycle can stable operation, computer running overload can also smooth operation and interpolation cycle adjustable, can adapt to a variety of different needs.
- Has 16 input port, input interface more simple, port of wet and dry contact can be, wiring is simple, dry contact method for as long as the external connected to a physical switch to the wire can be, all 16 input port are indication signal, for low power usually indicating lamp is bright, debugging simple and clear.
- With 8 output ports, a single output drive capability of 170mA max, can be directly driven by DC relay.
- The PWM speed output port can be set, the frequency of PWM, pulse width 0~1000 continuously adjustable.
- With the function of the speed, the actual speed of the spindle in the Mach3 interface, real-time display, accurate and stable measurement.
- With 256 bytes of NVRAM space, can save the coordinates of the 6 axes, the next power without the need to find the mechanical origin.
- The circuit board is made by the engineer, the design level is clear at a glance.


Revisions List


| | |
|---|----|
| ● Basic connection diagram (an Overview) | 3 |
| ● Mechanical dimensions diagram | 4 |
| ● Prepare Mach3 software | 5 |
| A. Installing the motion card plug-in. | 8 |
| B. Setup for Mach3 | 9 |
| ● Hardware installation of motion control card..... | 12 |
| 8 way control output pin position diagram..... | 16 |
| External power knob | 17 |
| Spindle speed PWM analog output | 19 |
| Probe connection..... | 23 |
| ● MPG Setting..... | 25 |
| Software configuration..... | 25 |
| MPG soft mode:..... | 26 |
| MPG hard mode..... | 27 |
| ● Using NVRAM and advace setting..... | 28 |

● Basic connection diagram (an Overview)



● Mechanical dimensions diagram





● Prepare Mach3 software



This card is a Mach3 USB interface 3/6 axes external motion card.



The latest version of Mach3 official website:
<http://www.machsupport.com/downloads.php>



Mach3 download: as shown below:



[Home](#) | [Downloads](#) | [Purchase](#) | [Support](#) | [Resources](#)

Downloads


For previous versions of Mach and LazyCam, XML's, and other Extra Information: [Click Here](#)

(Some of the older files are linked directly from the FTP server in order to avoid redundancy. If your download does not start immediately, please give it a few seconds - it's probably trying to contact/login to the FTP server.)



Installation the Mach3:

The Parallel Port Driver does not require.



Installation the software of the USB motion card

This USB motion card does not need install any USB driver, Windows2000/Xp/Vista/Windows7 can directly identify.


1. Connecting the USB cable to the PC and the motion card.




A. Installing the motion card plug-in.

Unzip the usbmove.zip, copy or drag usbmove.dll into your Mach3\PlugIns folder.


Note: Download the latest version of plug-in(nMotion.zip)




Start the Mach3 software, a dialogue of "Motion Control Hardware PlugIn sensed!!" is shown. Please select the "Mach3-USB-Motion-Card" you can also check "Don't ask me , this again".




B.




Engine Configuration... Ports & Pins




Motor config like this:(config=>Motor Tuning)



The Mach3 Menu => Config => Homing/Limits dialog Axes direction, depends on the "Reversed". if you have a MPG ,please let "Reversed" as "X" .




Or you can change the direction on this page: Dir Low selet "X" or "√"



b) Setup the input singles.

There are 16 general-purpose input channels. The channels number is from 1 to 16, Port Number is 2.


Suggest Active Low = "√" (Set Low signal Level for Inputs)



c) Setup the Output signals.

There are 8 general-purpose (open-drain) output channels, The channels number is from 9 to 16. Port Number is 2.

Suggest Active Low = "√" (Set Low signal Level for outputs)



● **Hardware installation of motion control card**

PIN function description

6 Axis Output Port

| Index | Pin Name | Function | Electrical characteristics | note |
|-------|----------|----------|----------------------------|-----------------|
| 1 | PU+ | Plus + | Differential signal | AM26LS31 output |
| 2 | PU- | Plus- | Differential signal | AM26LS31 output |
| 3 | Dir+ | Dir+ | Differential signal | AM26LS31 output |
| 4 | Dir- | Dir- | Differential signal | AM26LS31 output |


16 input terminals (Port Input) pin function description

| index | Pin Name | Function | Electrical characteristics | Note |
|-------|----------|----------------------------|--|--|
| 1 | GND | Digital signal ground wire | | |
| 2 | IN1 | Input Port | Type NPN switch or contact switch | <p>In the MACH3 menu “配置”=“端口和引脚” "Configuration" =>"port and pin" =>"Input Signals"中 配置功能 => "Input Signals" in the allocation of functions Mach3中端口号 (Port Number)为2, 针脚号(Pin Number) 为1~16号。 Mach3 in the port number (Number Port) for 2, the pin number (Number Pin) for the 1~16 number.</p> |
| 3 | IN2 | | | |
| 4 | IN3 | | | |
| 5 | IN4 | | | |
| 6 | IN5 | | | |
| 7 | IN6 | | | |
| 8 | IN7 | | | |
| 9 | IN8 | | | |
| 10 | IN9 | | | |
| 11 | IN10 | | | |
| 12 | IN11 | | | |
| 13 | IN12 | | | |
| 14 | IN13 | | | |
| 15 | IN14 | | | |
| 16 | IN15 | | | |
| 17 | IN16 | | | |
| 18 | GND | Digital signal ground wire | Digital ground , and 24V power supply ground is the same | |

Output terminal (Port Out) pin function description


| index | Pin Name | Function | Electrical characteristics | Note |
|-------|----------|--|---|---|
| 1 | 24V+ | 9~36V DC Power | Minimum power 10W | Power input terminal |
| 2 | GND | 9~36V DC GND | Minimum power 10W | |
| 3 | GND | Signal ground | Input power EGND and control output DGND are isolated | Input power EGND and control output DGND are isolated |
| 4 | 5V+ | output out:5V | max:600mA | Output from 24V to 5V linear power supply |
| 5 | 5V+ | | | |
| 6 | PWM | PWM pulsewidth | OC, 50V/170mA | The spindle speed output, output can be 0~5V or |
| 7 | SP+ | Speed Signal + | 6~15mA | LED Positive input |
| 8 | SP- | Speed Signal- | 6~15mA | LED Negative input |
| 9 | O16 | general-purpose (open-drain) output channels | OC (open-drain), 50V /50mA | In the MACH3 menu "Configuration" =>"port and pin" => "Output Signals" Configuration function, port number (Number Port) for 2, pin number (Number Pin) for the 8~16 number. |
| 10 | O15 | | | |
| 11 | O14 | | | |
| 12 | O13 | | | |
| 13 | O12 | general-purpose (open-drain) output channels | OC (open-drain), 100V /170mA | |
| 14 | O11 | | | |
| 15 | O10 | | | |
| 16 | O9 | | | |
| 17 | GND | Signal ground | Signal ground | Signal ground |
| 18 | PE | Grounding wire | Grounding wire | Grounding wire |

nMotion mach3 USB CNC controller




8 way control output pin position diagram

NPN type low level output mode, O9~12 have the maximum drive current 170mA.O13~16 50mA max.




Principle diagram of Isolate Output




External power knob

Two AI input port, the voltage input range of 0~3.3V, can be used to set the rate of FRO/SRO/JOG
Mach3 menu “Plugins Config”=>”Config”, enter “PlugIn Control and Activation”.




There are two kinds of application modes of analog quantity input: 1 absolute value model, 2 increment value model

As follows:




- The absolute value of FRO%, SRO%, Jog% under the mode of the value of a linear relationship with the AI, AI level is higher, the greater the value of the corresponding rate.
- Incremental value mode FRO%, SRO%, Jog% value with the relative change in volume changes, mainly referring to the last moment of external AI voltage value and present current AI voltage value comparison, if the voltage is relatively higher, corresponding to the rate value is increased, otherwise reduce.
- General incremental value model.
- FRO% (feed rate of F). SRO% (spindle speed ratio), Jog% (dynamic magnification) set external rate "ExtA1" or "ExtA2"


nMotion mach3 USB CNC controller



After the completion of the configuration, click "OK". Rotation rate knob Mach3 interface corresponding to the SRO%, FRO% numerical immediately change. Rotation rate knob, Mach3 interface corresponding to the Jog Rate% Slow value immediately change.




In absolute value mode will be more of a button, used to set the initial voltage of low level and high level at the end of the voltage, such as external input voltage range is 0.5V~2.5V, to rate value by the change of 0-300, low starting level voltage is 0.5V, the high level end voltage 2.5V. Click on the "AdvanceSet" the following dialog:




And a filtering coefficient, filter coefficient is small, rate value response faster, smoothing less, whereas response is slower, the change was more smooth. Generally do not move, set to 10~20 can be.

AI input port as shown below, not marked red terminal 4.4V about power, this power only potentiometer power supply, please don't external use.




Spindle speed PWM analog output

Click on the main menu "config" => "port and pins into the spindle spindle setup settings, tick the" use spindle motor output. In Freq. PWMBase, there is no need to fill in the required frequency. PWM frequency in the nMotion configuration page processing.




Spindle PWM (pulse width modulation output frequency in the Mach3 menu Config=>Config plugins into plugin control and selection of activation nMotion card to control the, click on the "config" after USB card configuration dialog.


nMotion mach3 USB CNC controller




spindle relay configuration





Phase configuration of spindle speed control signal PWM




Mach3 menu " Config=> Spindle Pulleys ", enter " Pulley Selection "




Principle diagram of the spindle speed control analog output interface






VCC 10V have not served , if you use a variable frequency speed control of the spindle and need in PWM feet pick a pull-up resistor to inverter 10V output ports.




nMotion control card of the speed of the input interface schematic




nMotion mach3 USB CNC controller



Probe connection



Config (Config => Ports and Pins)



Probe script like this:

FeedCurrent = GetOemDRO(818) 'Get the current settings, OEM DROs (818)=Feedrate
DRO

ZCurrent = GetOemDro(802)'OEM DROs (802)=Z DRO

GageH = GetOEMDRO(1001) 'OEMDRO(1001)=Gage Block Height

ZNew = ZCurrent - 20 'probe down 20 mm

Code "G90F100" 'slow feed rate to 100 MM/MIN

Rem Code "G4 P1" 'Pause 1 second to give time to position probe plate

Code "G31 Z" &ZNew

While IsMoving()

Sleep(10)

Wend

Call SetDro (2,GageH) 'DRO(2)=Z DRO

nMotion mach3 USB CNC controller

FinalMove = GageH + 10

Code "G0 Z" &FinalMove

Code "F" &FeedCurrent

'restore starting feed rate

● MPG Setting



MPG use the input pin IN15 and IN16 , connect to Encode A and B signal.

If you use a full function MPG with Rate switch and Axis select,


The DB15 head PIN order is like this :

| | | | |
|---|------------|----|------------|
| 1 | +5V | 9 | Encoder A |
| 2 | | 10 | Encoder B |
| 3 | C axis SEL | 11 | GND |
| 4 | ESTOP | 12 | A axis SEL |
| 5 | B Axis SEL | 13 | Z axis SEL |
| 6 | X1 | 14 | Y axis SEL |
| 7 | X10 | 15 | X axis SEL |
| 8 | X100 | | |


Software configuration

Mach3 electronic hand wheel configuration, as shown below: (Config => Ports and Pins)

nMotion mach3 USB CNC controller



Press "TAB" key, like this



MPG soft mode: (no longer use)

This mode fix the MPG with Mach3, so all this need mach3 to do MPG work.



Press "Shuttle Mode" button, Shuttle Mode LED is off, the MPG woke on Soft mode.

MPG hard mode

Press "Shuttle Mode" button, Shuttle Mode LED is on, the MPG woke on Hard mode.



If your MPG have a white button as Enable, please hold the white button all the time when you use the MPG to control the machine.


In hard mode, the plugin set need to set something.

nMotion mach3 USB CNC controller


1. MPG Mini Step, in “X1”, the MPG 1 step need to move a short distance, this need to set the “Config Plugins”, and there is a setting like this, “MPG Set” ->”Min Step”.



2. fifth Axis selection (no longer use)



If you want to use the BSEL pin to select C Axis ,you can set the config like this below.



● Using NVRAM

Select “PC save”, the position is saved in PC ,and Select”NVRAM”, the Mechanical position saved in NVRAM.

nMotion mach3 USB CNC controller

Motion Status & Config 15502169252@126.com

✕

Status

 nMotion Powered On
 Limit or Estop hit
 Probe Hit
 nMotion in Pause
 nMotion in Wait condition
 Interpolated move in progress
 Velocity move in progress
 Scan in progress

Firmware version: 0.0

Outputs Enable

Selected for output enable

| | |
|-------------------------------------|---------|
| <input checked="" type="checkbox"/> | OUT9EN |
| <input checked="" type="checkbox"/> | OUT10EN |
| <input checked="" type="checkbox"/> | OUT11EN |
| <input checked="" type="checkbox"/> | OUT12EN |
| <input checked="" type="checkbox"/> | OUT13EN |
| <input checked="" type="checkbox"/> | OUT14EN |
| <input checked="" type="checkbox"/> | OUT15EN |
| <input checked="" type="checkbox"/> | OUT16EN |

All ins and outs are in Mach3

| | |
|-------------------------------|--------------------------------|
| Outputs->Mach Pins | |
| <input type="checkbox"/> Out1 | <input type="checkbox"/> Out9 |
| <input type="checkbox"/> Out2 | <input type="checkbox"/> Out10 |
| <input type="checkbox"/> Out3 | <input type="checkbox"/> Out11 |
| <input type="checkbox"/> Out4 | <input type="checkbox"/> Out12 |
| <input type="checkbox"/> Out5 | <input type="checkbox"/> Out13 |
| <input type="checkbox"/> Out6 | <input type="checkbox"/> Out14 |
| <input type="checkbox"/> Out7 | <input type="checkbox"/> Out15 |
| <input type="checkbox"/> Out8 | <input type="checkbox"/> Out16 |

| | |
|-------------------------------|--------------------------------|
| Inputs->MachPins | |
| <input type="checkbox"/> Pin1 | <input type="checkbox"/> Pin9 |
| <input type="checkbox"/> Pin2 | <input type="checkbox"/> Pin10 |
| <input type="checkbox"/> Pin3 | <input type="checkbox"/> Pin11 |
| <input type="checkbox"/> Pin4 | <input type="checkbox"/> Pin12 |
| <input type="checkbox"/> Pin5 | <input type="checkbox"/> Pin13 |
| <input type="checkbox"/> Pin6 | <input type="checkbox"/> Pin14 |
| <input type="checkbox"/> Pin7 | <input type="checkbox"/> Pin15 |
| <input type="checkbox"/> Pin8 | <input type="checkbox"/> Pin16 |

Analog Config

ABS Incremental

FRO%:

SRO%:

JOG%:

Configs

Servo Cycle Time: Seconds per

Last position save
 PC save NVRAM

MPG Set

Min Step:

G Code Buffer:

Spindle

Pulse per turn:

PWM Frequency: KHz

Homing

No Homing
 Single Stage -H inputs
 Dual stage- H inputs

Home Switches
 X Y Z A

Homing Pull Off

| | | | |
|------------|--------------------------------|------------|--------------------------------|
| X Pull Off | <input type="text" value="3"/> | A Pull Off | <input type="text" value="3"/> |
| Y Pull Off | <input type="text" value="3"/> | B Pull Off | <input type="text" value="3"/> |
| Z Pull Off | <input type="text" value="3"/> | C Pull Off | <input type="text" value="3"/> |

Five Axis Sel: B Axis C Axis

Device Connect

USB EtherNet

nMotion IP Address:

● Advance Setting

Advance Setting ✕

IN Call Setting

| | | | |
|--|--|---|---|
| <input type="checkbox"/> IN1 Call For Code"M901" | <input type="checkbox"/> IN5 Call For Code"M905" | <input type="checkbox"/> IN9 Call For Code"M909" | <input type="checkbox"/> IN13 Call For Code"M913" |
| <input type="checkbox"/> IN2 Call For Code"M902" | <input type="checkbox"/> IN6 Call For Code"M906" | <input type="checkbox"/> IN10 Call For Code"M910" | <input type="checkbox"/> IN14 Call For Code"M914" |
| <input type="checkbox"/> IN3 Call For Code"M903" | <input type="checkbox"/> IN7 Call For Code"M907" | <input type="checkbox"/> IN11 Call For Code"M911" | <input type="checkbox"/> IN15 Call For Code"M915" |
| <input type="checkbox"/> IN4 Call For Code"M904" | <input type="checkbox"/> IN8 Call For Code"M908" | <input type="checkbox"/> IN12 Call For Code"M912" | <input type="checkbox"/> IN16 Call For Code"M916" |

Motion Pin config


| | | | |
|---|---|--|--|
| X_STEP: <input type="text" value="XS"/> | A_STEP: <input type="text" value="AS"/> | X Axis: <input type="text" value="Step+Dir"/> | Y Axis Mode: <input type="text" value="Step+Dir"/> |
| X_DIR: <input type="text" value="XD"/> | A_DIR: <input type="text" value="AD"/> | Z Axis Mode: <input type="text" value="Step+Dir"/> | A Axis: <input type="text" value="Step+Dir"/> |
| Y_STEP: <input type="text" value="YS"/> | B_STEP: <input type="text" value="BS"/> | B Axis Mode: <input type="text" value="Step+Dir"/> | C Axis: <input type="text" value="Step+Dir"/> |
| Y_DIR: <input type="text" value="YD"/> | B_DIR: <input type="text" value="BD"/> | CS Function Select: <input checked="" type="radio"/> Step Or Dir out <input type="radio"/> Spindle Step Set | |
| Z_STEP: <input type="text" value="ZS"/> | C_STEP: <input type="text" value="CS"/> | | |
| Z_DIR: <input type="text" value="ZD"/> | C_DIR: <input type="text" value="CD"/> | | |

Offline MPG Work

Reset Offline MPG Set


1. use INPUT pin to call a M Code run:(this only work when mach3 is in stop statue),M901~M916 is write by your self.

nMotion mach3 USB CNC controller



2. change the STEP and DIR pin order


You can change the X axis step to any pin of XS, XD, YS,.....CS, CD. Use this configure function.



3. change CS pin function

CS pin of step and dir prot can set to Step or DIR out for Motion axis ,or as spindle step out.


If you use a servo as spindle .




4. offline MPG work function

If you want to use MPG to control machine to move with out start the computer, you can use this function , set all the configure as your machine work, and then, select the function, press "OK" button, some data will write to nMotion card. and then the next time , you no need to open the computer, you can also use MPG to move axis. This can only work when your MPG ESTOP button was press down, or your MPG have no ESTOP button.

nMotion mach3 USB CNC controller




5. nMotion CNC controller support Step/Dir Motor as spindle.



When you select to use Step/dir Motor like this above, the spindle speed control by step speed, if CS function is not set to spindle mode, '09' will be the step pin for spindle, '010' will be the direction of spindle.

And us 'CS' function as Spindle mode, 'CS' will be the step pin for spindle. 'CD' will be the Dir pin for spindle.

Spindle motor configure as below,



"Step per" refers to the number of pulses required for each rotation of the spindle. This is different from X, Y, Z or A, B, C axis. And Acceleration of spindle also need to set.